Certificate number: o60223309i246287-A-1



Calibration Certificate



Customer **UPSTATE MEDICAL PHYSICS** BLOSSOM DR 1290 14564 VICTOR US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586

USA

+1-833-296-9240 customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 R/F

Serial number Manufacturer

246287

RaySafe

CALIBRATION INFORMATION

As found As left

2/7/2023 2/9/2023

Adjustment done

Yes

Tested by

Amber Ramos

Joseph Hertl

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/13/2023

CALIBRATION RESULT

AS FOUND:

All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 %, Air kerma rate: 5 %

Time: 0.5 %, Voltage: 2 %





Certificate number: o60223309i246287-B-1



Calibration Certificate

Customer **UPSTATE MEDICAL PHYSICS** BLOSSOM DR 1290 14564 VICTOR US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 USA +1-833-296-9240 customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 R/F

Serial number

246287

Manufacturer

RaySafe

CALIBRATION INFORMATION

As found

2/7/2023

As left

2/9/2023

Adjustment done

Yes

Tested by

Amber Ramos

Joseph Hertl

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/13/2023



Certificate number: o60223336i246200-A-1



Calibration Certificate



Customer **UPSTATE MEDICAL PHYSICS** BLOSSOM DR 1290 **14564 VICTOR** US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 **USA**

+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

X2 MAM

Serial number Manufacturer

246200 RaySafe CALIBRATION INFORMATION

As found

2/8/2023

As left

2/8/2023

Adjustment done

Yes

Tested by

Elijah Thompson

Joseph Hertl

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/13/2023

CALIBRATION RESULT

All measured and tested values of this certificate were found to be in conformance with the AS FOUND:

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air Kerma: 5 %

Voltage: 2 % or 0.5 kV (without paddle), 2 % or 0.7 kV (with paddle)





Certificate number: o60223336i246200-B-1



Calibration Certificate

Customer **UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290** 14564 VICTOR US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 **USA** +1-833-296-9240 customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 MAM

Serial number

246200 RaySafe

Manufacturer

CALIBRATION INFORMATION As found

2/8/2023

As left

2/8/2023

Adjustment done

Yes

Tested by

Elijah Thompson

Joseph Hertl

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/13/2023





Certificate number: o60223380i229999-1



Calibration Certificate



Customer **UPSTATE MEDICAL PHYSICS** BLOSSOM DR 1290 **14564 VICTOR** US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 USA

+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number X2 Survey 229999

Manufacturer

RaySafe

CALIBRATION INFORMATION

As found As left

2/8/2023 2/8/2023

Adjustment done

Yes

Channell Kennedy Tested by

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/13/2023

CALIBRATION RESULT

AS FOUND:

All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 % (RQA), 10 % (N-series)





Certificate number: o60223330i256791-1



Calibration Certificate



Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 USA +1-833-296-9240 customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number X2 CT

Manufacturer

256791 RaySafe CALIBRATION INFORMATION

As found

2/8/2023 2/8/2023

As left

Adjustment done

Yes

Tested by

Channell Kennedy

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/13/2023

CALIBRATION RESULT

AS FOUND:

All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 %





Certificate number: o60223353i232789-1



Calibration Certificate

Customer
UPSTATE MEDICAL PHYSICS
BLOSSOM DR 1290
14564 VICTOR

Laboratory
Unfors RaySafe Inc.
2 Science Road
Glenwood, IL 60425-1586
USA
+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 Light

Serial number Manufacturer 232789 RaySafe CALIBRATION INFORMATION

As found

2/8/2023 2/9/2023

As left Adjustment done

Yes

Tested by

Channell Kennedy

Elijah Thompson

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/13/2023

CALIBRATION RESULT

AS FOUND:

One or more measured and tested values of this certificate are outside of the specifications by a

margin less than the expanded measurement uncertainty. Therefore, it is not possible to state

non-conformance with specifications for those measurements.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Illuminance: 3 % Luminance: 3 %



