Certificate number: o60227510i246291-A-1



Calibration Certificate



Customer **UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR** US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586

USA +1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number

Manufacturer

X2 R/F 246291

RaySafe

CALIBRATION INFORMATION

As found As left

5/25/2023 6/5/2023 Yes

Adjustment done Tested by

Amber Ramos Rosio Ramos

Approved by

Josefina Diaz

Finalization technician

Certificate date

6/9/2023

CALIBRATION RESULT

AS FOUND:

All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 %, Air kerma rate: 5 %

Time: 0.5 %, Voltage: 2 %

This laboratory is accredited according to ISO/IEC 17025:2017 by the American Association for Laboratory Accreditation (A2LA) and the results shown in this certificate have been determined within the scope of accreditation unless stated otherwise in this certificate.





Certificate number: o60227510i246291-B-1



Calibration Certificate

Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 USA

+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number X2 R/F 246291

Manufacturer

RaySafe

CALIBRATION INFORMATION

As found As left 5/25/2023 6/5/2023

Adjustment done

Yes

Tested by

Amber Ramos

Rosio Ramos

Approved by

Josefina Diaz

Finalization technician

Certificate date

6/9/2023





Certificate number: o60227523i267808-A-1



Calibration Certificate



Customer **UPSTATE MEDICAL PHYSICS** BLOSSOM DR 1290 **14564 VICTOR** US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 **USA**

+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number

Manufacturer

267808 RaySafe

X2 MAM

CALIBRATION INFORMATION

As found As left

5/26/2023 6/6/2023

Adjustment done

Yes

Tested by

Armad Bryant Channell Kennedy Kierra Sullivan Nate Barnes Tommy Cox

Approved by

Josefina Diaz

Einalization technician

Certificate date

6/9/2023

CALIBRATION RESULT

AS FOUND:

One or more measured and tested values of this certificate are within the specifications by a margin

less than the expanded measurement uncertainty. Therefore, it is not possible to state conformance

with specifications for those measurements.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air Kerma: 5 %

Voltage: 2 % or 0.5 kV (without paddle), 2 % or 0.7 kV (with paddle)

This laboratory is accredited according to ISO/IEC 17025:2017 by the American Association for Laboratory Accreditation (A2LA) and the results shown in this certificate have been determined within the scope of accreditation unless stated otherwise in this certificate.





Certificate number: o60227523i267808-B-1



Calibration Certificate

Customer **UPSTATE MEDICAL PHYSICS** BLOSSOM DR 1290 14564 VICTOR US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586

USA

+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number Manufacturer

X2 MAM 267808 RaySafe

As found As left

Adjustment done

Tested by

CALIBRATION INFORMATION

5/26/2023 6/6/2023 Yes

Armad Bryant

Channell Kennedy Kierra Sullivan Nate Barnes Tommy Cox

Approved by

Josefina Diaz

Finalization technician

Certificate date

6/9/2023





Certificate number: o60227424i230095-1



Calibration Certificate



Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 USA

+1-833-296-9240 customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 Survey

Serial number Manufacturer 230095 RaySafe CALIBRATION INFORMATION

As found

5/24/2023

As left

5/25/2023 Yes

Tested by

Tommy Cox

Approved by

Adjustment done

Josefina Diaz

Finalization technician

Certificate date

6/9/2023

CALIBRATION RESULT

AS FOUND:

All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 % (RQA), 10 % (N-series)

This laboratory is accredited according to ISO/IEC 17025:2017 by the American Association for Laboratory Accreditation (A2LA) and the results shown in this certificate have been determined within the scope of accreditation unless stated otherwise in this certificate.





Certificate number: o60227375i263739-1



Calibration Certificate



Customer **UPSTATE MEDICAL PHYSICS** BLOSSOM DR 1290 14564 VICTOR US

Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 **USA**

+1 - 833 - 296 - 9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 CT

Serial number Manufacturer

263739

RaySafe

CALIBRATION INFORMATION

As found

5/24/2023 5/24/2023

As left Adjustment done

Tested by

Yes

Tommy Cox

Approved by

Josefina Diaz

Finalization technician 6/9/2023

Certificate date

CALIBRATION RESULT

AS FOUND:

All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 %

This laboratory is accredited according to ISO/IEC 17025:2017 by the American Association for Laboratory Accreditation (A2LA) and the results shown in this certificate have been determined within the scope of accreditation unless stated otherwise in this certificate.





Certificate number: o60227376i232730-1



Calibration Certificate

Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586 USA

+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 Light

Serial number Manufacturer 232730 RaySafe CALIBRATION INFORMATION

As found As left 5/24/2023 5/25/2023

Adjustment done

Yes

Tested by

Joseph Hertl

Approved by

Josefina Diaz

Finalization technician

Certificate date

6/9/2023

CALIBRATION RESULT

AS FOUND:

One or more measured and tested values of this certificate are within the specifications by a margin

less than the expanded measurement uncertainty. Therefore, it is not possible to state conformance

with specifications for those measurements.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Illuminance: 3 % Luminance: 3 %



